



Day : Monday  
Date: 8/15/2005

Time: 16:50:33

## Inventor Name Search

Enter the **first few letters** of the Inventor's Last Name.  
Additionally, enter the **first few letters** of the Inventor's First name.

**Last Name**

**First Name**

To go back use Back button on your browser toolbar.

Back to [PALM](#) | [ASSIGNMENT](#) | [OASIS](#) | [Home page](#)

	Type	L #	Hits	Search Text	DBs	Time Stamp
1	BRS	L1	170	408/712.ccls.	US- PGPUB; USPAT; EPO; JPO; DERWEN T; IBM_TD B	2005/08/15 16:37
2	BRS	L2	1803	408/709.ccls. or 408/67.ccls. or 408/72B.ccls. or 408/97.ccls. or 408/115R.ccls. or 408/115B.ccls. or 408/202.ccls. or 408/241B.ccls.	US- PGPUB; USPAT	2005/08/15 16:41
3	BRS	L3	1759	408/1r.ccls. or 408/110.ccls. or 408/241s.ccls. or 408/79.ccls. or 408/80.ccls. or 408/81.ccls.	US- PGPUB; USPAT	2005/08/15 16:45
4	BRS	L4	1026	29/402.01.ccls. or 29/402.09.ccls. or 29/402.16.ccls. or 29/402.18.ccls. or 29/402.19.ccls.	US- PGPUB; USPAT	2005/08/15 16:48
5	BRS	L5	0	Kamphius-Dwain.in.	US- PGPUB; USPAT	2005/08/15 16:48
6	BRS	L6	0	Kamphius-Dwain-L.in.	US- PGPUB; USPAT	2005/08/15 16:49
7	BRS	L7	0	Kamphuis-Dwain.in.	US- PGPUB; USPAT	2005/08/15 16:49
8	BRS	L8	10	Kamphuis-Dwain-l.in.	US- PGPUB; USPAT	2005/08/15 16:52
9	BRS	L9	2373	(liner and trim\$4) and (vacuum or suct\$6)	US- PGPUB; USPAT	2005/08/15 16:56

	Comments	Error Definition	Errors
1			
2			
3			
4			
5			
6			
7			
8			
9			

	Type	L #	Hits	Search Text	DBs	Time Stamp
10	BRS	L10	443	9 and outlet	US- PGPUB; USPAT	2005/08/15 16:56
11	BRS	L11	301	10 and inlet	US- PGPUB; USPAT	2005/08/15 16:56
12	BRS	L12	10	8 and engine	US- PGPUB; USPAT	2005/08/15 16:57
13	BRS	L13	105	(engine and liner) and (trim\$4 and clamp)	US- PGPUB; USPAT	2005/08/15 17:00
14	BRS	L14	64	13 and hole	US- PGPUB; USPAT	2005/08/15 16:59
15	BRS	L15	39	14 and thread\$4	US- PGPUB; USPAT	2005/08/15 16:59
16	BRS	L16	248	(engine and liner) and (trim\$4 and plug)	US- PGPUB; USPAT	2005/08/15 17:02
17	BRS	L17	29	16 and (debris or chips)	US- PGPUB; USPAT	2005/08/15 17:01
18	BRS	L18	140	(engine and liner) and (suction or vacuum) and (trim\$4 and coupl\$3)	US- PGPUB; USPAT	2005/08/15 17:03
19	BRS	L19	5	18 and misalignment	US- PGPUB; USPAT	2005/08/15 17:04
20	BRS	L20	588	409/132.ccls.	US- PGPUB; USPAT; EPO; JPO; DERWEN T; IBM_TD B	2005/08/15 17:06

	Comments	Error Definition	Errors
10			
11			
12			
13			
14			
15			
16			
17			
18			
19			
20			

	Type	L #	Hits	Search Text	DBs	Time Stamp
21	BRS	L21	294	29/888.061.ccls.	US- PGPUB; USPAT; EPO; JPO; DERWEN T; IBM_TD B	2005/08/15 17:23

	Comments	Error Definition	Errors
21			